

2023 Grinder Pump Fee Table

Item #	Part	Customer Price
1	D001B14B10BG Simplex Chamber, Cover, 54" Bury Depth, 32' cable w/out pump	\$2,420
2	DH071-93 Simplex Chamber, Cover, Sentry Panel, 54" Bury Depth, 32' cable including pump. DH071-124 with special approval	\$6,050
3	D200A01A01AA Extreme Pump	\$3,960
4	NC0047G01 Extreme Series 2' Extension w/ band clamp and cover shroud, no lid	\$796
5	NC0047G03 Extreme Series 4' Extension w/ band clamp and cover shroud, no lid	\$893
6	PC1112G02 200 Series Accessway replacement kit, simplex (200 Series lids are no longer available)	\$1,006
7	9615 Replacement Lid 2000	\$104
8	SA1A010B0AA Simplex 240 V Sentry Control Panel	\$520
9	ND0082G01 6" Riser Kit	\$331
10	NC0022G11 Replacement cover w/ shroud and band clamp	\$360
11	ND0059G01 Conversion Kit 200 Series Tank w/ Extreme Core	\$133
12	ND0058G01 Conversion Kit 2000 Series Tank w/ Extreme Core	\$82
13	ND0036G07 Extreme Cable 50'	\$284
14	ND0036G08 Extreme Cable 75'	\$360
15	ND0036G09 Extreme Cable 100'	\$436
16	Ballast Block	\$770

As part of construction, Is property owner relocating Grinder Pump Chamber?

If Yes – Property Owner Will Need to Purchase the Following Items:

Grinder Pump Chamber (Item #1 Above)

Control Panel (Item #8 Above)

The Grinder Panel includes 32' of cable, additional cable may be required (Item #16, #17 & #18 Above)

If No – Property Owner Will Need to Purchase the Following Items:

Control Panel (Item #8 Above)

The Grinder Panel includes 32' of cable, additional cable may be required (Item #16, #17 & #18 Above)

Note: The property owner must protect the existing pump chamber during construction activities. If the existing chamber is damaged, a new one will need to be purchased – Item #1 above

All other items shown Above are charged if the municipality has to replace the item due to damage, and are assessed on a case by case basis.